VitaGuard™


BY VITA DIGITAL

Land checks for buyers who can't be there

FREE PLOT SCREEN

Satellite flood & terrain check

MOT-KE-49AEBB67 · 3 Nov 2026



Copernicus Sentinel-2, 11 Feb 2026 · 1.2 km across · gold ring = 50 m, dashed = 500 m

RESULT

Lower flood-risk signal

Lower | Moderate | Higher

ELEVATION

2043 m

above sea level

SLOPE

7%

across the pin

ABOVE LOW GROUND

48 m

vs lowest point within 500 m

WATER WITHIN 50 M

Never

seen by Landsat, 1984–2021

Open water near the pin, 1984–2021

Your pin

0 | 100 m | 200 m | 300 m | 400 m | 500 m

No open water seen within 500 m in 37 years of Landsat images.

0% of the land within 500 m has ever been under water

Why this result

- No surface water seen nearby in 37 years of Landsat imagery, and the pin is not in a local low spot.

PIN (WGS 84)	COUNTRY	PARCEL REF	MAP
-1.24650, 36.66320	Kenya	VIN-KE-1246-36663-49AE	Open in Google Maps

Where this fits

✓ — 2 — 3

Free plot screen
Done
Elevation, slope and 37 years of surface-water history for this pin.

Licensed surveyor
You pay
You hire them to check the beacons and chart the plot at Kenya Ministry of Lands Ardhisasa & RIMS Registry.

Plot Watch
$9 a month
Radar and satellite photos on every pass; email with before and after images if the plot changes.

What this screen can't tell you

It is a desk check, not a survey: it does not check title, ownership, boundaries or government acquisition. Landsat misses flooding under trees and short flash floods; water data ends in 2021. Elevation has several metres of error.

Vita Digital LLC (US). VitaGuard is a desk and field verification service; it is not legal or title advice.